



# NMSU Fire Department

## 2024 Annual Fire Safety Report

### Clery Act Requirement



New Mexico State University  
Fire Safety Reporting [18] HEOA  
Reporting Date: January 1, 2023 to December 31, 2023

---

*NOTE: All fire drills reported below are supervised, meet International Fire Code Chapter 4 Emergency Planning and Preparedness, and have mandatory evacuation for all individuals. During the fire drills there is an inspection of: audio sound, synchronization of light strobes, exit doors, and other factors of the system in place.*

---

#### **I. On-campus student housing facilities, description of the facilities and description of fire safety system.**

##### **Residence Halls**

###### **Garcia Hall (1715 International Mall)**

Garcia Hall is a three-story fire resistive building with four patios. Dorm rooms encircle the patios.

Fire Protection: Dorm rooms contain individual smoke detectors. Pull stations and smoke alarms in the common areas are monitored by a fire alarm system. The fire alarm system is inspected/tested annually and maintained to NFPA 72: National Fire Alarm and Signaling Code, and it reports directly to NMSU PD dispatch center. Rooms and main areas are protected by an automatic wet pipe sprinkler system. The fire sprinkler system is inspected quarterly and maintained to NFPA 25: Standard for the Inspection, Testing, and Maintenance of. Water-Based Fire Protection Systems.

- Fire Drill: 1 on September 11, 2023
- Fire Drill: 2 on November 6, 2023

No fires reported. Information is in section **II Fire Statistics**.

###### **Piñon Hall (1780 East University Avenue)**

Piñon Hall is a three-story wood frame structure. The building is two separate sections connected by a common area. Fire Protection: Dorm rooms contain individual smoke detectors. Pull stations and smoke alarms in the common areas are monitored by a fire alarm system. The fire alarm system is inspected/tested annually and maintained to NFPA 72: National Fire Alarm and Signaling Code, and it reports directly to NMSU PD dispatch center. Rooms and main areas are protected by an automatic wet pipe sprinkler system. The fire sprinkler system is inspected quarterly and maintained to NFPA 25: Standard for the Inspection, Testing, and Maintenance of. Water-Based Fire Protection Systems.



# NMSU Fire Department

## 2024 Annual Fire Safety Report

### Clery Act Requirement



- Fire Drill: 1 on September 12, 2023
- Fire Drill: 2 on November 6, 2023

No fires reported. Information is in section [II Fire Statistics](#).

#### **Rhodes-Garrett-Hamiel (RGH) (2715-2735 Jordan Road)**

RGH is a two-story fire resistive building with traditional dorm rooms off the main hallway.

Fire Protection: Dorm rooms contain individual smoke detectors. Pull stations in the common areas are monitored by a fire alarm system. The fire alarm system is inspected/tested annually and maintained to NFPA 72: National Fire Alarm and Signaling Code, and it reports directly to NMSU PD dispatch center. Hallways and corridors are protected by with an automatic wet pipe sprinkler system. The fire sprinkler system is inspected quarterly and maintained to NFPA 25: Standard for the Inspection, Testing, and Maintenance of. Water-Based Fire Protection Systems.

- Fire Drill: 1 on September 5, 2023
- Fire Drill: 2 on November 6, 2023

No fires reported. Information is in section [II Fire Statistics](#).

#### **Juniper Hall (1525 International Mall)**

Juniper Hall is a three-story wood frame building with traditional dorm rooms off the main hallway.

Fire Protection: Dorm rooms contain interconnected smoke detectors with modular tone system tied into a full building fire alarm. Pull stations in the common areas are monitored by a fire alarm system. The fire alarm system is inspected/tested annually and maintained to NFPA 72: National Fire Alarm and Signaling Code, and it reports directly to NMSU PD dispatch center. Rooms, hallways, public areas, and corridors are protected with an automatic wet pipe sprinkler system. The fire sprinkler system is inspected quarterly and maintained to NFPA 25: Standard for the Inspection, Testing, and Maintenance of. Water-Based Fire Protection Systems.

- Fire Drill: 1 on September 5, 2023
- Fire Drill: 2 on November 6, 2023

No fires reported. Information is in section [II Fire Statistics](#).



# NMSU Fire Department

## 2024 Annual Fire Safety Report

### Clery Act Requirement



#### Campus Apartments

##### Cervantes Village

Cervantes Village are multiple single story wood frame buildings, they contain one, two, and four bedroom apartments.

Fire Protection: The rooms contain individual smoke detectors and CO alarm detectors.

No fires reported. Information is in section II [Fire Statistics](#).

##### Chamisa Village I & II (1735 Stewart Street)

Chamisa Village is a complex made-up of three-story wood frame buildings. Apartments come in two and four bedroom layouts.

Fire Protection: Apartments contain individual smoke detectors. Pull stations and smoke alarms in the common areas are monitored by a fire alarm system. The fire alarm system is inspected/tested annually and maintained to NFPA 72: National Fire Alarm and Signaling Code, and it reports directly to NMSU PD dispatch center. Rooms and main areas are protected by an automatic wet pipe sprinkler system. The fire sprinkler system is inspected quarterly and maintained to NFPA 25: Standard for the Inspection, Testing, and Maintenance of Water-Based Fire Protection Systems.

##### Chamisa Village – Patio A

- Fire Drill: 1 on September 12, 2023
- Fire Drill: 2 on November 7, 2023

##### Chamisa Village – Patio B

- Fire Drill: 1 on September 12, 2023
- Fire Drill: 2 on November 7, 2023

##### Chamisa Village – Patio C

- Fire Drill: 1 on September 12, 2023
- Fire Drill: 2 on November 7, 2023



# NMSU Fire Department

## 2024 Annual Fire Safety Report

### Clery Act Requirement



#### Chamisa Village – Patio E

- Fire Drill: 1 on September 12, 2023
- Fire Drill: 2 on November 7, 2023

#### Chamisa Village – Patio F

- Fire Drill: 1 on September 12, 2023
- Fire Drill: 2 on November 7, 2023

#### Chamisa Village – Patio G

- Drill: 1 on September 12, 2023
- Drill: 2 on November 7, 2023

#### Chamisa Village – Patio H

- Fire Drill: 1 on September 12, 2023
- Fire Drill: 2 on November 7, 2023

No fires reported. Information is in section [II Fire Statistics](#).

#### **Vista Del Monte (3540 Research Road)**

Vista Del Monte is a complex made up of two story wood frame buildings. Apartments are in two-bedroom configuration.

Fire Protection: Apartments contain individual smoke detectors and CO detectors.

No fires reported. Information is in section [II Fire Statistics](#).

### **Family Housing**

#### **Tom Fort and Sutherland Villages**

Tom Fort and Sutherland are single-family, single story fire resistive homes.

Fire Protection: The homes contain individual smoke detectors and CO detectors.

No fires reported. Information is in section [II Fire Statistics](#).



# NMSU Fire Department

## 2024 Annual Fire Safety Report

### Clery Act Requirement



#### Sorority Housing

##### Chi Omega (1700 East University Avenue)

Chi Omega is a residential sorority, two story wood frame home.

Fire Protection: Bedrooms contain individual smoke detectors. Smoke alarms in the common areas are monitored by a fire alarm system. The fire alarm system is inspected/tested annually and maintained to NFPA 72: National Fire Alarm and Signaling Code, and it reports directly to NMSU PD dispatch center. Rooms and common areas are covered by an automatic wet pipe sprinkler system. The fire sprinkler system is inspected quarterly and maintained to NFPA 25: Standard for the Inspection, Testing, and Maintenance of. Water-Based Fire Protection Systems.

- Fire Drill: 1 on October 10, 2022
- Fire Drill: 2 on November 6, 2023

No fires reported. Information is in section [II Fire Statistics](#).

##### Delta Zeta (1600 East University Avenue)

Delta Zeta is a residential sorority, single story wood frame home.

Dorm rooms contain individual smoke detectors. Smoke alarms in the common areas are monitored by a fire alarm system. The fire alarm system is inspected/tested annually and maintained to NFPA 72: National Fire Alarm and Signaling Code, and it reports directly to NMSU PD dispatch center. Rooms and common areas are covered by an automatic wet pipe sprinkler system. The fire sprinkler system is inspected quarterly and maintained to NFPA 25: Standard for the Inspection, Testing, and Maintenance of. Water-Based Fire Protection Systems.

- Fire Drill: 1 on September 5, 2023
- Fire Drill: 2 on November 6, 2023

No fires reported. Information is in section [II Fire Statistics](#).

##### Zeta Tau Alpha (1699 East University Avenue)

Zeta Tau Alpha is a residential sorority, two story wood frame home.

Fire Protection: Smoke detectors throughout the building and pull stations in the hallways are monitored by a fire alarm system. The fire alarm system is inspected/tested annually and maintained to NFPA 72:



# NMSU Fire Department

## 2024 Annual Fire Safety Report

### Clery Act Requirement



National Fire Alarm and Signaling Code, and it reports directly to NMSU PD dispatch center. Rooms and common areas are covered by an automatic wet pipe sprinkler system. The fire sprinkler system is inspected quarterly and maintained to NFPA 25: Standard for the Inspection, Testing, and Maintenance of Water-Based Fire Protection Systems.

- Fire Drill: 1 on September 5, 2023
- Fire Drill: 2 on November 6, 2023

No fires reported. Information is in section II [Fire Statistics](#).

### Academic Buildings

#### **Aggie Book Store Building #632 (1400 E. University Avenue / 2710 Jordan Street)**

Aggie Book Store is a two-story non-combustible building that houses offices, restaurants, and mercantile showrooms containing books, clothes, and NMSU campus memorabilia.

Fire Protection: Aggie Book Store is equipped with a full addressable fire alarm system and sprinkler system. The fire alarm system is inspected/tested annually and maintained to NFPA 72: National Fire Alarm and Signaling Code, and it reports directly to NMSU PD dispatch center. The fire sprinkler system is inspected quarterly and maintained to NFPA 25: Standard for the Inspection, Testing, and Maintenance of Water-Based Fire Protection Systems.

- Fire Drill on September 27, 2023

No fires reported. Information is in section II [Fire Statistics](#).

#### **ASNMSU Center for the Arts ( 1000 East University Ave.)**

ASNMSU Center for the Arts Building is a three-story non-combustible building that houses offices, classrooms, auditorium and common areas.

Fire Protection: ASNMSU Center for the Arts Building is equipped with a full addressable fire alarm system and is covered by an automatic wet pipe sprinkler system. The fire alarm system is inspected/tested annually and maintained to NFPA 72: National Fire Alarm and Signaling Code, and it reports directly to NMSU PD dispatch center. The fire sprinkler system is inspected quarterly and maintained to NFPA 25: Standard for the Inspection, Testing, and Maintenance of Water-Based Fire Protection Systems.



# NMSU Fire Department

## 2024 Annual Fire Safety Report

### Clery Act Requirement



- Fire Drill on September 15, 2023

No fires reported. Information is in section II [Fire Statistics](#).

#### **Astronomy Building (1320 Frenger Mall)**

The Astronomy Building is a three-story non-combustible building that houses offices, classrooms and common areas.

Fire Protection: The Astronomy Building is equipped with a full addressable fire alarm system.. The fire alarm system is inspected/tested annually and maintained to NFPA 72: National Fire Alarm and Signaling Code, and it reports directly to NMSU PD dispatch center. Fire Drill on September 18, 2023

No fires reported. Information is in section II [Fire Statistics](#).

#### **Branson Library (1305 Frenger Mall)**

Branson Library is a four-story Fire Resistive building that houses offices, a library and common areas.

Fire Protection: Branson Library Building is equipped with a full addressable fire alarm system and is covered by an automatic wet pipe sprinkler system. The fire alarm system is inspected/tested annually and maintained to NFPA 72: National Fire Alarm and Signaling Code, and it reports directly to NMSU PD dispatch center. The fire sprinkler system is inspected quarterly and maintained to NFPA 25: Standard for the Inspection, Testing, and Maintenance of. Water-Based Fire Protection Systems.

- Fire Drill on September 11, 2023

No fires reported. Information is in section II [Fire Statistics](#).

#### **Business Complex (1320 University Ave.)**

Business complex is a three-story non-combustible building that houses offices, classrooms and common areas.

Fire Protection: Business Complex Building is equipped with a full addressable fire alarm system and is covered by an automatic wet pipe sprinkler system. The fire alarm system is inspected/tested annually and maintained to NFPA 72: National Fire Alarm and Signaling Code, and it reports directly to NMSU PD



# NMSU Fire Department

## 2024 Annual Fire Safety Report

### Clery Act Requirement



dispatch center. The fire sprinkler system is inspected quarterly and maintained to NFPA 25: Standard for the Inspection, Testing, and Maintenance of. Water-Based Fire Protection Systems.

- Fire Drill on February 8, 2023.

No fires reported. Information is in section II [Fire Statistics](#).

#### **Chemistry Building -“55” (1175 N. Horseshoe)**

Chemistry Building- “55” is a two-story fire resistive building that houses offices, classrooms and common areas.

Fire Protection: Chemistry Building -“55” is equipped with a full addressable fire alarm system and is covered by an automatic wet pipe sprinkler system. The fire alarm system is inspected/tested annually and maintained to NFPA 72: National Fire Alarm and Signaling Code, and it reports directly to NMSU PD dispatch center. The fire sprinkler system is inspected quarterly and maintained to NFPA 25: Standard for the Inspection, Testing, and Maintenance of. Water-Based Fire Protection Systems.

- Fire Drill on September 15, 2023

No fires reported. Information is in section II [Fire Statistics](#).

#### **Chemistry Building – “65” (1175 N. Horseshoe)**

Chemistry Building- “65” is a three-story non-combustible building that houses offices, classrooms and common areas.

Fire Protection: Chemistry Building- “65” is equipped with a full addressable fire alarm system and is covered by an automatic wet pipe sprinkler system. The fire alarm system is inspected/tested annually and maintained to NFPA 72: National Fire Alarm and Signaling Code, and it reports directly to NMSU PD dispatch center. The fire sprinkler system is inspected quarterly and maintained to NFPA 25: Standard for the Inspection, Testing, and Maintenance of. Water-Based Fire Protection Systems.

- Fire Drill on September 15, 2023

No fires reported. Information is in section II [Fire Statistics](#).





# NMSU Fire Department

## 2024 Annual Fire Safety Report

### Clery Act Requirement



#### **Clara Belle Williams Communication Building (1405 International Mall)**

Clara Belle Williams Communication Building is a three-story non-combustible building that houses offices, classrooms and common areas.

Fire Protection: Clara Belle Williams Communication Building is equipped with a full addressable fire alarm system and is covered by an automatic wet pipe sprinkler system. The fire alarm system is inspected/tested annually and maintained to NFPA 72: National Fire Alarm and Signaling Code, and it reports directly to NMSU PD dispatch center. The fire sprinkler system is inspected quarterly and maintained to NFPA 25: Standard for the Inspection, Testing, and Maintenance of. Water-Based Fire Protection Systems.

- Fire Drill on September 22, 2023

No fires reported. Information is in section [II Fire Statistics](#).

#### **Clinton P. Anderson Building (1050 Stewart St. )**

Clinton P. Anderson Building is a three-story non-combustible building that houses offices, research, fabrication, carpentry shop and common areas.

Fire Protection: Clinton P. Anderson Building is equipped with a full addressable fire alarm system and is covered by an automatic wet pipe sprinkler system. The fire alarm system is inspected/tested annually and maintained to NFPA 72: National Fire Alarm and Signaling Code, and it reports directly to NMSU PD dispatch center. The fire sprinkler system is inspected quarterly and maintained to NFPA 25: Standard for the Inspection, Testing, and Maintenance of. Water-Based Fire Protection Systems.

- October 11, 2023

No fires reported. Information is in section [II Fire Statistics](#).

#### **Computer Center (1275 Stewart St.)**

Computer Center Building is a two-story non-combustible building that houses offices, classrooms and common areas.

Fire Protection: Computer Center Building is equipped with a full addressable fire alarm system and is covered by an automatic wet pipe sprinkler system. The fire alarm system is inspected/tested annually and



# NMSU Fire Department

## 2024 Annual Fire Safety Report

### Clery Act Requirement



maintained to NFPA 72: National Fire Alarm and Signaling Code, and it reports directly to NMSU PD dispatch center. The fire sprinkler system is inspected quarterly and maintained to NFPA 25: Standard for the Inspection, Testing, and Maintenance of. Water-Based Fire Protection Systems.

- Fire Drill on September 11, 2023

No fires reported. Information is in section [II Fire Statistics](#).

#### **Corbett Center Student Union**

Corbett Center Student Union Building is a three-story Non-Combustible building that houses offices, auditorium, ballroom, dining and common areas.

Fire Protection: Corbett Center Student Union Building is equipped with a full addressable fire alarm system and is covered by an automatic wet pipe sprinkler system. The fire alarm system is inspected/tested annually and maintained to NFPA 72: National Fire Alarm and Signaling Code, and it reports directly to NMSU PD dispatch center. The fire sprinkler system is inspected quarterly and maintained to NFPA 25: Standard for the Inspection, Testing, and Maintenance of. Water-Based Fire Protection Systems.

- Fire Drill on December 9, 2023

No fires reported. Information is in section [II Fire Statistics](#).

#### **Devasthali Hall ( 1308 University Ave.)**

Devasthali Hall Building is a three-story non-combustible building that houses offices, art gallery, work shop and common areas.

Fire Protection: Devasthali Hall Building is equipped with a full addressable fire alarm system and is covered by an automatic wet pipe sprinkler system. The fire alarm system is inspected/tested annually and maintained to NFPA 72: National Fire Alarm and Signaling Code, and it reports directly to NMSU PD dispatch center. The fire sprinkler system is inspected quarterly and maintained to NFPA 25: Standard for the Inspection, Testing, and Maintenance of. Water-Based Fire Protection Systems.

- Fire Drill on September 27, 2023

No fires reported. Information is in section [II Fire Statistics](#).



# NMSU Fire Department

## 2024 Annual Fire Safety Report

### Clery Act Requirement



#### Dove Hall (1305 North Horseshoe)

Dove Hall Building is a two-story non-combustible building that houses offices, classrooms and common areas.

Fire Protection: Dove Hall Building is equipped with a full addressable fire alarm. The fire alarm system is inspected/tested annually and maintained to NFPA 72: National Fire Alarm and Signaling Code, and it reports directly to NMSU PD dispatch center.

- Fire Drill on February 8, 2023

No fires reported. Information is in section II [Fire Statistics](#).

#### Educational Services Building (1780 East University)

Educational Services Building is a single-story non-combustible building that houses office, assembly space and common areas.

Fire Protection: Educational Services Building is equipped with a full addressable fire alarm system and is covered by an automatic wet pipe sprinkler system. The fire alarm system is inspected/tested annually and maintained to NFPA 72: National Fire Alarm and Signaling Code, and it reports directly to NMSU PD dispatch center. The fire sprinkler system is inspected quarterly and maintained to NFPA 25: Standard for the Inspection, Testing, and Maintenance of. Water-Based Fire Protection Systems.

- Fire Drill on March 21, 2023

No fires reported. Information is in section II [Fire Statistics](#).

#### Engineering Complex I (1025 Stewart)

Engineering Complex 1 Building is a two-story non-combustible building that houses offices, classrooms, fabrication shop and common areas.

Fire Protection: Engineering Complex 1 Building is equipped with a full addressable fire alarm system and is covered by an automatic wet pipe sprinkler system. The fire alarm system is inspected/tested annually and maintained to NFPA 72: National Fire Alarm and Signaling Code, and it reports directly to NMSU PD dispatch center. The fire sprinkler system is inspected quarterly and maintained to NFPA 25: Standard for the Inspection, Testing, and Maintenance of. Water-Based Fire Protection Systems.

- Fire Drill on September 27, 2023



# NMSU Fire Department

## 2024 Annual Fire Safety Report

### Clery Act Requirement



No fires reported. Information is in section II [Fire Statistics](#).

#### **Engineering Complex II (3035 S. Espina)**

Engineering Complex 2 Building is a two-story non-combustible building that houses offices, classrooms and common areas.

Fire Protection: Engineering Complex 2 Building is equipped with a full addressable fire alarm system and is covered by an automatic wet pipe sprinkler system. The fire alarm system is inspected/tested annually and maintained to NFPA 72: National Fire Alarm and Signaling Code, and it reports directly to NMSU PD dispatch center. The fire sprinkler system is inspected quarterly and maintained to NFPA 25: Standard for the Inspection, Testing, and Maintenance of. Water-Based Fire Protection Systems.

- Fire Drill on September 19, 2023

No fires reported. Information is in section II [Fire Statistics](#).

#### **Engineering Complex 3 (1060 Frenger Mall)**

Engineering Complex 3 Building is a three-story non-combustible building that houses offices, classrooms and common areas.

Fire Protection: Engineering Complex 3 Building is equipped with a full addressable fire alarm system and is covered by an automatic wet pipe sprinkler system. The fire alarm system is inspected/tested annually and maintained to NFPA 72: National Fire Alarm and Signaling Code, and it reports directly to NMSU PD dispatch center. The fire sprinkler system is inspected quarterly and maintained to NFPA 25: Standard for the Inspection, Testing, and Maintenance of. Water-Based Fire Protection Systems.

- Fire Drill on September 27, 2023

No fires reported. Information is in section II [Fire Statistics](#).

#### **Football Coaches Office (1810 Stewart St.)**

Football Coaches Office Building is a single-story non-combustible building that houses offices, classrooms and common areas.

Fire Protection: Football Building is equipped with a full addressable fire alarm system and is covered by an automatic wet pipe sprinkler system. The fire alarm system is inspected/tested annually and maintained to NFPA 72: National Fire Alarm and Signaling Code, and it reports directly to NMSU PD dispatch center. The



# NMSU Fire Department

## 2024 Annual Fire Safety Report

### Clery Act Requirement



fire sprinkler system is inspected quarterly and maintained to NFPA 25: Standard for the Inspection, Testing, and Maintenance of Water-Based Fire Protection Systems.

- Fire Drill on February 8, 2023

No fires reported. Information is in section II [Fire Statistics](#).

#### **Frenger Food Court (1420 Frenger Mall)**

Frenger Food Court Building is a single-story non-combustible building that houses, food preparation, dining and common areas.

Fire Protection: Frenger Food Court Building is equipped with a full addressable fire alarm system. The fire alarm system is inspected/tested annually and maintained to NFPA 72: National Fire Alarm and Signaling Code, and it reports directly to NMSU PD dispatch center.

- Fire Drill on September 27, 2023

No fires reported. Information is in section II [Fire Statistics](#).

#### **Garcia Center (3024 Andrew Wall Place)**

Garcia Center Building is a two-story non-combustible building that houses offices, classrooms and common areas.

Fire Protection: Garcia Center Building is equipped with a full addressable fire alarm system. The fire alarm system is inspected/tested annually and maintained to NFPA 72: National Fire Alarm and Signaling Code, and it reports directly to NMSU PD dispatch center..

- Fire Drill on February 8, 2023, 2023

No fires reported. Information is in section II [Fire Statistics](#).

#### **Goddard Hall (1100 Horseshoe)**

Goddard Hall Building is a three-story non-combustible building that houses offices, classrooms and common areas.

Fire Protection: Goddard Hall Building is equipped with a full addressable fire alarm system and is covered by an automatic wet pipe sprinkler system. The fire alarm system is inspected/tested annually and



# NMSU Fire Department

## 2024 Annual Fire Safety Report

### Clery Act Requirement



maintained to NFPA 72: National Fire Alarm and Signaling Code, and it reports directly to NMSU PD dispatch center. The fire sprinkler system is inspected quarterly and maintained to NFPA 25: Standard for the Inspection, Testing, and Maintenance of. Water-Based Fire Protection Systems.

- Fire Drill on September 11, 2023

No fires reported. Information is in section [II Fire Statistics](#).

#### **Golf Club Clubhouse Building #597 (3500 Herb Wimberly Drive)**

**Golf Club Clubhouse** is a single-story with garage non-combustible building that houses offices, garage, mercantile, a restaurant, assembly areas, and cooking areas.

Fire Protection: Golf Club Clubhouse is equipped with a full addressable fire alarm system and is covered by an automatic wet pipe sprinkler system. The fire alarm system is inspected/tested annually and maintained to NFPA 72: National Fire Alarm and Signaling Code, and it reports directly to NMSU PD dispatch center. The fire sprinkler system is inspected quarterly and maintained to NFPA 25: Standard for the Inspection, Testing, and Maintenance of. Water-Based Fire Protection Systems.

- Fire Drill on September 25, 2023

No fires reported. Information is in section [II Fire Statistics](#).

#### **Hadley Hall (2650 Weddell St.)**

Hadley Hall is a two-story with a basement Fire Resistive building that houses offices, and common areas.

Fire Protection: Hadley Hall is equipped with a full addressable fire alarm system. The fire alarm system is inspected/tested annually and maintained to NFPA 72: National Fire Alarm and Signaling Code, and it reports directly to NMSU PD dispatch center.

- Fire Drill on September 11, 2023

No fires reported. Information is in section [II Fire Statistics](#).

#### **Hardman Jacobs**

Hardman Jacobs is a two-story non-combustible building that houses offices, classrooms and assembly areas.



# NMSU Fire Department

## 2024 Annual Fire Safety Report

### Clery Act Requirement



Fire Protection: Hardman Jacobs is equipped with a full addressable fire alarm system and sprinkler system. The fire alarm system is inspected/tested annually and maintained to NFPA 72: National Fire Alarm and Signaling Code, and it reports directly to NMSU PD dispatch center. The fire sprinkler system is inspected quarterly and maintained to NFPA 25: Standard for the Inspection, Testing, and Maintenance of Water-Based Fire Protection Systems.

- Fire Drill on September 14, 2023

No fires reported. Information is in section II [Fire Statistics](#).

#### **Health and Social Services ( 1355 International Mall)**

Health and Social Services Building is a three-story non-combustible building that houses offices, and classrooms.

Fire Protection: Educational Services is equipped with a full addressable fire alarm system and sprinkler system. The fire alarm system is inspected/tested annually and maintained to NFPA 72: National Fire Alarm and Signaling Code, and it reports directly to NMSU PD dispatch center. The fire sprinkler system is inspected quarterly and maintained to NFPA 25: Standard for the Inspection, Testing, and Maintenance of Water-Based Fire Protection Systems.

- Fire Drill on September 22, 2023

No fires reported. Information is in section II [Fire Statistics](#).

#### **James B. Delamater Activity Center**

James B. Delamater Building is a two-story non-combustible building that houses offices, gymnasium, weight room and common areas.

Fire Protection: James B. Delmater is equipped with a full addressable fire alarm system. The fire alarm system is inspected/tested annually and maintained to NFPA 72: National Fire Alarm and Signaling Code, and it reports directly to NMSU PD dispatch center.

- Fire Drill on September 12, 2023

No fires reported. Information is in section II [Fire Statistics](#).



# NMSU Fire Department

## 2024 Annual Fire Safety Report

### Clery Act Requirement



#### Jett Hall

Jett Hall Building is a two-story non-nombustible building that houses offices, classrooms, chemical lab and assembly areas.

Fire Protection: Jett Hall is equipped with a full addressable fire alarm system and sprinkler system. The fire alarm system is inspected/tested annually and maintained to NFPA 72: National Fire Alarm and Signaling Code, and it reports directly to NMSU PD dispatch center. The fire sprinkler system is inspected quarterly and maintained to NFPA 25: Standard for the Inspection, Testing, and Maintenance of. Water-Based Fire Protection Systems.

- Fire Drill on September 21, 2023

No fires reported. Information is in section II [Fire Statistics](#).

#### Kent Hall

Kent Hall is a two-story non-combustible building that houses offices, art gallery and common areas.

Fire Protection: Kent Hall is equipped with a full addressable fire alarm system. The fire alarm system is inspected/tested annually and maintained to NFPA 72: National Fire Alarm and Signaling Code, and it reports directly to NMSU PD dispatch center.

- Fire Drill on February 8, 2023

No fires reported. Information is in section II [Fire Statistics](#).

#### Music Building (1975 N. Horseshoe)

Music Building is a two-story non-combustible building that houses offices, and assembly areas.

Fire Protection: Music Building is equipped with a full addressable fire alarm system and sprinkler system. The fire alarm system is inspected/tested annually and maintained to NFPA 72: National Fire Alarm and Signaling Code, and it reports directly to NMSU PD dispatch center. The fire sprinkler system is inspected quarterly and maintained to NFPA 25: Standard for the Inspection, Testing, and Maintenance of. Water-Based Fire Protection Systems.

- Fire Drill on September 15, 2023

No fires reported. Information is in section II [Fire Statistics](#).





# NMSU Fire Department

## 2024 Annual Fire Safety Report

### Clery Act Requirement



#### **Natorium ( 1520 Stewart St.)**

Natorium is a single-story fire resistive building that houses offices, indoor/outdoor swimming areas.

Fire Protection: Natatorium is equipped with a full addressable fire alarm system. The fire alarm system is inspected/tested annually and maintained to NFPA 72: National Fire Alarm and Signaling Code, and it reports directly to NMSU PD dispatch center

- Fire Drill on September 11, 2023

No fires reported. Information is in section II [Fire Statistics](#).

#### **Pan American Center Building #284 (1810 E. University Avenue)**

Pan American Center is a two-story non-combustible building that houses offices, a sports arena, gymnasium, assembly areas, and cooking areas.

Fire Protection: Pan American Center is equipped with a full addressable fire alarm system and is covered by an automatic wet pipe sprinkler system. The fire alarm system is inspected/tested annually and maintained to NFPA 72: National Fire Alarm and Signaling Code, and it reports directly to NMSU PD dispatch center. The fire sprinkler system is inspected quarterly and maintained to NFPA 25: Standard for the Inspection, Testing, and Maintenance of. Water-Based Fire Protection Systems.

- Fire Drill on September 21, 2023

No fires reported. Information is in section II [Fire Statistics](#).

#### **Pete Domenici Institute for Public Policy (3014 Mc Fie Circle)**

Pete Domenici Institute for Public Policy is a two-story non-combustible building that houses offices, and assembly areas.

Fire Protection: Pete Domenici Institute for Public Policy is equipped with a full addressable fire alarm system and sprinkler system. The fire alarm system is inspected/tested annually and maintained to NFPA 72: National Fire Alarm and Signaling Code, and it reports directly to NMSU PD dispatch center. The fire sprinkler system is inspected quarterly and maintained to NFPA 25: Standard for the Inspection, Testing, and Maintenance of. Water-Based Fire Protection Systems.

- Fire Drill on February 8, 2023



# NMSU Fire Department

## 2024 Annual Fire Safety Report

### Clery Act Requirement



No fires reported. Information is in section II [Fire Statistics](#).

#### Science Hall (1290 Frenger Mall)

Science Hall is a three-story non-combustible building that houses offices, class rooms and common areas.

Fire Protection: Science Hall is equipped with a full addressable fire alarm system and is covered by an automatic wet pipe sprinkler system. The fire alarm system is inspected/tested annually and maintained to NFPA 72: National Fire Alarm and Signaling Code, and it reports directly to NMSU PD dispatch center. The fire sprinkler system is inspected quarterly and maintained to NFPA 25: Standard for the Inspection, Testing, and Maintenance of. Water-Based Fire Protection Systems.

- Fire Drill on September 19, 2023

No fires reported. Information is in section II [Fire Statistics](#).

#### Stan Fulton Center

Stan Fulton Center Building is a three-story non-combustible building that houses offices, dining, athletic viewing and common areas.

Fire Protection: Stan Fulton is equipped with a full addressable fire alarm system and is covered by an automatic wet pipe sprinkler system. The fire alarm system is inspected/tested annually and maintained to NFPA 72: National Fire Alarm and Signaling Code, and it reports directly to NMSU PD dispatch center. The fire sprinkler system is inspected quarterly and maintained to NFPA 25: Standard for the Inspection, Testing, and Maintenance of. Water-Based Fire Protection Systems.

- Fire Drill on September 13, 2023

No fires reported. Information is in section II [Fire Statistics](#).

#### Stuckey Hall Building # 282 (3170 S. Espina Street)

Stuckey Hall is a single-story Fire Resistive building that houses offices.

Fire Protection: Stuckey Hall is not equipped with a fire alarm system or sprinkler system.

No fires reported. Information is in section II [Fire Statistics](#).



# NMSU Fire Department

## 2024 Annual Fire Safety Report

### Clery Act Requirement



#### Tejada Building (3005 Knox St.)

Tejada Building is a single-story non-combustible building that houses offices, commercial cooking and common areas.

Fire Protection: Tejada Building is equipped with a full addressable fire alarm system. The fire alarm system is inspected/tested annually and maintained to NFPA 72: National Fire Alarm and Signaling Code, and it reports directly to NMSU PD dispatch center. Fire Drill on September 12, 2023

No fires reported. Information is in section II [Fire Statistics](#).

#### Tennis Center ( 1400 Wells St.)

Tennis Center Building is single-story non-combustible building that houses offices, tennis courts and common areas.

Fire Protection: Tennis Center is equipped with a full addressable fire alarm system. The fire alarm system is inspected/tested annually and maintained to NFPA 72: National Fire Alarm and Signaling Code, and it reports directly to NMSU PD dispatch center

- Fire Drill on September 15, 2023

No fires reported. Information is in section II [Fire Statistics](#).

#### Thomas and Brown

Thomas and Brown is a three-story non-combustible building that houses offices and classrooms.

Fire Protection: Thomas and Brown is equipped with a full addressable fire alarm system and is covered by an automatic wet pipe sprinkler system. The fire alarm system is inspected/tested annually and maintained to NFPA 72: National Fire Alarm and Signaling Code, and it reports directly to NMSU PD dispatch center. The fire sprinkler system is inspected quarterly and maintained to NFPA 25: Standard for the Inspection, Testing, and Maintenance of. Water-Based Fire Protection Systems.

- Fire Drill on September 14, 2023

No fires reported. Information is in section II [Fire Statistics](#).



# NMSU Fire Department

## 2024 Annual Fire Safety Report

### Clery Act Requirement



#### **Young Hall (1300 S. Horseshoe)**

Young Hall is a two-story non-combustible building that houses offices and storage.

Fire Protection: Young Hall is equipped with a full addressable fire alarm system. The fire alarm system is inspected/tested annually and maintained to NFPA 72: National Fire Alarm and Signaling Code, and it reports directly to NMSU PD dispatch center. Fire Drill on September 21, 2023

- Fire Drill on September 11, 2023

No fires reported. Information is in section II [Fire Statistics](#).

#### **Dona Ana Community College**

##### **DACC Alex Sanchez Building #341 (3400 South Espina Street)**

DACC Alex Sanchez is a single-story non-combustible building that houses offices, machine shop, classroom areas, dining and a computer server complex.

Fire Protection: DACC Alex Sanchez is equipped with a full addressable an automatic Inergen fire suppression system in its main-frame computer area, a fire alarm system, and is covered by an automatic wet pipe sprinkler system. The Inergen system is inspected annually and maintained to NFPA 2001: Standard on Clean Agent Fire Extinguishing Systems. The fire alarm system is inspected/tested annually and maintained to NFPA 72: National Fire Alarm and Signaling Code, and it reports directly to NMSU PD dispatch center. The fire sprinkler system is inspected quarterly and maintained to NFPA 25: Standard for the Inspection, Testing, and Maintenance of. Water-Based Fire Protection Systems.

No fires reported. Information is in section II [Fire Statistics](#).

##### **DACC Classroom Building #480 (3400 South Espina Street)**

DACC Classroom Building is a two-story non-combustible building that houses offices, lecture rooms, classrooms, chemical labs and common areas.

Fire Protection: DACC Classroom Building is equipped with a full addressable fire alarm system and is covered by an automatic wet pipe sprinkler system. The fire alarm system is inspected/tested annually and maintained to NFPA 72: National Fire Alarm and Signaling Code, and it reports directly to NMSU PD



# NMSU Fire Department

## 2024 Annual Fire Safety Report

### Clery Act Requirement



dispatch center. The fire sprinkler system is inspected quarterly and maintained to NFPA 25: Standard for the Inspection, Testing, and Maintenance of. Water-Based Fire Protection Systems.

No fires reported. Information is in section II [Fire Statistics](#).

#### **DACC Health & Public Services Building #540 (3400 South Espina Street)**

DACC Health & Public Services Building is a two-story non-combustible building that houses offices, classrooms and common areas.

Fire Protection: DACC Health & Public Services Building is equipped with a full addressable fire alarm system and is covered by an automatic wet pipe sprinkler system. The fire alarm system is inspected/tested annually and maintained to NFPA 72: National Fire Alarm and Signaling Code, and it reports directly to NMSU PD dispatch center. The fire sprinkler system is inspected quarterly and maintained to NFPA 25: Standard for the Inspection, Testing, and Maintenance of. Water-Based Fire Protection Systems.

No fires reported. Information is in section II [Fire Statistics](#).

#### **Learning Resource Center Building #479 (3400 South Espina Street)**

Learning Resource Center is a two-story non-combustible building that houses offices, classrooms, and common areas.

Fire Protection: Learning Resource Center is equipped with a full addressable fire alarm system and is covered by an automatic wet pipe sprinkler system. The fire alarm system is inspected/tested annually and maintained to NFPA 72: National Fire Alarm and Signaling Code, and it reports directly to NMSU PD dispatch center. The fire sprinkler system is inspected quarterly and maintained to NFPA 25: Standard for the Inspection, Testing, and Maintenance of. Water-Based Fire Protection Systems.

No fires reported. Information is in section II [Fire Statistics](#).

#### **Trades Center Building #357 (3400 South Espina Street)**

Trades Center Building is a single-story non-combustible building that houses offices, laboratories, classroom areas, and open bay areas.

Fire Protection: Trades Center Building is equipped with a full addressable fire alarm system and is covered by an automatic wet pipe sprinkler system. The fire alarm system is inspected/tested annually and maintained to NFPA 72: National Fire Alarm and Signaling Code, and it reports directly to NMSU PD



# NMSU Fire Department

## 2024 Annual Fire Safety Report

### Clery Act Requirement



dispatch center. The fire sprinkler system is inspected quarterly and maintained to NFPA 25: Standard for the Inspection, Testing, and Maintenance of. Water-Based Fire Protection Systems.

No fires reported. Information is in section II [Fire Statistics](#).

#### **Fires in Residential Halls, Campus Apartments, Family Housing, and Sorority Housing**

- None reported.

Information is in section II [Fire Statistics](#).

#### **Fires in Academic Buildings**

- None reported.

Information is in section II [Fire Statistics](#).

#### **Fatality or Casualty Fires**

**None reported.**

#### **Arson Fires**

**None reported.**



# NMSU Fire Department

## 2024 Annual Fire Safety Report

### Clery Act Requirement



## II. Fire Statistics

### 2023 Digital Fire Log

#### FIRES INSIDE STRUCTURES

DATE	ADDRESS	INCIDENT

#### FIRES OUTSIDE STRUCTURES

DATE	ADDRESS	INCIDENT



# NMSU Fire Department

## 2024 Annual Fire Safety Report

### Clery Act Requirement



### III. New Mexico State University Fire Prevention Guidelines and Practices

Found online at: <https://fire.nmsu.edu/fire-prevention-guidelines/>

### IV. 2024 Annual Security Report, New Mexico State University Police Department

Found online at: <https://www.nmsupolice.com/safety/annual-reports.html>

New Mexico State University Fire Department offers free Portable Fire Extinguisher Training. To sign up for a class, go to Training Central: <https://trainingcentral.nmsu.edu/>.